

## JACK SHAFT

### Triumph Stag

Part Number: **214789**



### **VERY IMPORTANT – PLEASE READ BEFORE FITTING**

Why are you replacing your jackshaft? If it is because of worn gears, then this may be of interest to you.

The most common cause of jackshaft failure is a worn engine block as this can cause low oil feed to the water pump drive gear.

It is imperative that on removal of the old jackshaft the engine block is accurately measured to see whether the wear falls within the tolerance laid down by the manufacturer.

If excessive wear is found the engine block should be machined and bushed accordingly. Failure to do this will result in terminal damage to the engine.

**Replacement of this item should only be carried out by a suitably qualified individual.**

#### QUALITY PARTS AND ACCESSORIES



Triumph House, Sleaford Road, Bracebridge Heath, Lincoln LN4 2NA, England

UK Tel: +44 (0)1522 568000 | USA Tel: 1 855 746 2767 | Fax: +44 (0)1522 567600 | E-mail: [sales@rimmerbros.com](mailto:sales@rimmerbros.com)

**[www.rimmerbros.com](http://www.rimmerbros.com)**



A BRITISH COMPANY SUPPORTING BRITISH CARS

**QUALITY PARTS AND ACCESSORIES**



Triumph House, Sleaford Road, Bracebridge Heath, Lincoln LN4 2NA, England

UK Tel: +44 (0)1522 568000 | USA Tel: 1 855 746 2767 | Fax: +44 (0)1522 567600 | E-mail: [sales@rimmerbros.com](mailto:sales@rimmerbros.com)

**[www.rimmerbros.com](http://www.rimmerbros.com)**

Registered in England No. 2155394